# Weathertzenton Assistance

# Work Order Bid (ID)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/17017UC-0594/1

Work Order Type: Weatherization

Audit Name: 17017UC-0594

**CLIENT INFORMATION** 

Client ID: 17017UC-0594

#### **AGENCY INFORMATION**

Client ID: 17017UC-0594

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:
Cookeville, TN 38506 Email Address:

Agency Contact: Pridgeon, Wayne Work Phone:

Cell Phone: (931) 273-9616

Email Address:

Company Name & License Number:	
Contractor's Signature:	

### <u>COMMENT</u>

## **Measures**

Client ID: 17017UC-0594

N	leasure 1 Infil	tration Redctn			Componen	ts			Inspected
Co	CAULK INSTAL	EXTERIOR OF 10 WIND EXT. OF 6 DOORS LL 5 DOOR SWEEPS AN HERSTRIP 5 DOORS US	ID 1 THRE			HERST	RIP		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Miscellaneous Supplies	Infiltration Reduction	Each	1					
Oi	ther Detail								
				Measur	e Sub Total:			Sub Total:	
						. 00			Inanasta
N	fleasure 2 Win	dow Replacement			Componen	ts C3			Inspected
N		dow Replacement			Componen Estimated			Actual	Inspected
N Cc		dow Replacement  Description / Comment	Units	Qty	•		Qty		Inspected Total
M Cc	omment	·	<i>Units</i> SqFt	<b>Qty</b> 48	Estimated		Qty	Actual	
M C C C	omment Material / Labor	Description / Comment			Estimated		Qty	Actual	
M Cc 4 1 2	omment  Material / Labor  Windows	Description / Comment Window Replacement	SqFt	48	Estimated		Qty	Actual	
M Cc 4 1 2	Material / Labor Windows Labor	Description / Comment Window Replacement	SqFt	48	Estimated		Qty	Actual	
M Cc 4 1 2	Material / Labor Windows Labor	Description / Comment Window Replacement	SqFt	48	Estimated		Qty	Actual	
<b>N C c t t</b> 1 2	Material / Labor Windows Labor	Description / Comment Window Replacement	SqFt SqFt	48	Estimated			Actual	

	Measure 3 DWI	H Tank Insulation			Componer	its			Inspected
C	Comment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
		R-10 minimum-use bubble wrap							
2	Labor	DHW Tank Insulation	Each	1					
(	Other Detail								
				Measure	e Sub Total:			Sub Total:	
	Field Notes:								
L						. DO E	4.07		lmana ata d
		m Windows			Componer	its D9,E1	1,07		Inspected
C	Comment 4 WIND	OVVS			Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Windows	Storm Window	SqFt	32.44			]		
		<99 U.Iea. Under 100 UI	·						
2	Labor	Storm Window	SqFt	32.44					
3	Other	Storm Window	Each Window	4					
		<99 U.I ea Over 100 UI							
(	Other Detail			1			1		
L									
							7	_	
_				Measure	e Sub Total:			Sub Total:	
	Field Notes:			Measure	e Sub Total:			Sub Total:	
	Field Notes:			Measure	e Sub Total:			Sub Total:	
	Field Notes:			Measure	e Sub Total:			Sub Total:	

Client ID: 17017UC-0594

	<i>Measure</i> 5 Wir	ndow Replacement			Componen	ts B10			Inspected
C	Comment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Window Replacement	SqFt	15					
2	Labor	Window Replacement	SqFt	6.333					
(	Other Detail			1					
L									
L									
				Measure	e Sub Total:			Sub Total:	
	Field Notes:								
			Work O	rder Gra	nd Total:		Gran	d Total:	

Client ID: 17017UC-0594